

# RIDGELINE® T2 FULL BRIM

## 6-POINT RATCHET REPLACEMENT SUSPENSION WITH Mips®

UNRIVALED STYLE, ELEVATED PERFORMANCE



### HPT2R561M

#### MATERIALS

Elevate V2 Low Friction Layer: PK (Polyketone)
Sweat Band: Coolmax Fabric + PU (Polyurethane) Foam + Brush Nylon
Other Plastics: HDPE (Polypropylene) + Nylon
Straps: Nylon

⚠ WARNING: Cancer and Reproductive Harm –P65Warnings.ca.gov

#### GENERAL SPECIFICATIONS

Weight: 141.75 g
Dimensions: 21.59 x 18.42 x 12.7 cm
Suspension Adjust Sizing: 6.5 to 8
Suspension: Adjustable with Ratcheting Wheel

**i** The replacement suspension for the Ridgeline T2 Full Brim with Mips is sold separately and includes the sweat band. A standalone replacement sweat band is available (HPT2RBANDM).

Updated as of 02.26

#### ROTATIONAL IMPACTS

The Mips® system is designed to provide added safety for helmets in many accidents. For certain impacts, the Mips system can reduce harmful rotational motion that might otherwise be transferred to the user's head.

#### INSTRUCTIONS

##### 6-Point Strap Removal

1. Remove the suspension from the hard hat.
2. Place the suspension with the Mips® layer up and the ratchet knob towards you.
3. Slide the horizontal 6-point strap out of the suspension.
4. Install the 4-point suspension back into the hard hat.

##### Suspension Assembly

1. Insert tab into slot and push down until tab locks in place. Repeat for all tabs.
2. Push down the suspension until it is firmly in place.
3. Turn knob to fit the suspension to proper head size.

**i** When inserting suspension, front of hat can be determined by markings on the underside of the brim.



#### LEARN MORE

About the Mips® Safety System Technology