

RIDGELINE® T2 FULL BRIM

Mips® REPLACEMENT SWEAT BAND

UNRIVALED STYLE, ELEVATED PERFORMANCE



HPT2RBANDM

MATERIALS

Coolmax Fabric + PU (Polyurethane) Foam +
Brush Nylon

⚠ WARNING: Cancer and Reproductive Harm –P65Warnings.ca.gov

GENERAL SPECIFICATIONS

Weight: 11 g

Dimensions: 35.56 x 7.62 x 0.64 cm

i HPT2RBANDM is a replacement sweat band for Ridgeline T2 Full Brim with Mips® safety system and is only compatible with that system.

INSTRUCTIONS

To Remove Sweat Band from Suspension

1. Unhook the elastic sweatband straps from front of the suspension. There are a total of 4 hooks.
2. Slide the sweatband off the edge of each end. There are a total of two ends.
3. The sweat band is now removed from the suspension.

To Replace Sweat Band on Suspension

1. The end with elastic loops should be closest to the hooks. The end with the ventilated flaps should be closest to the openings of the Mips® layer.
2. Slide each (2) end of the sweat band in the edge of the Mips® yellow layer.
3. Hook the elastic loops onto the hooks. (There are a total of 4.)



LEARN MORE
About the Mips® Safety
System Technology

Updated as of 02.26