

RIDGELINE® T2 CHIN STRAP

UNRIVALED STYLE, ELEVATED PERFORMANCE

The Ridgeline T2 Chin Strap is designed to enhance the Ridgeline T2 Hard Hat with improved safety and comfort. This durable strap ensures a secure fit, providing peace of mind in various work environments. Its interchangeable design allows for easy replacement when the strap becomes dirty or sweaty, ensuring continuous protection and comfort for wearers.



HPT2STRAP

FEATURES

Hygienic Solution: Enables wearer to effortlessly replace a dirty or sweaty strap, promoting cleanliness and comfort

Secure Fit: The 4-point design ensures a snug and secure fit for maximum safety

Comfortable Wear: Adjustable features ensure comfort throughout the workday

Durable Construction: Made from high-quality materials, the chin strap is built to last

MATERIALS

Upper Chin Strap: Terylene
Lower Chin Strap: PU [Polyurethane] + Cotton Blend
Buckles: POM [Polyoxymethylene]

⚠ WARNING: Cancer and Reproductive Harm –P65Warnings.ca.gov

GENERAL SPECIFICATIONS

Weight: 56.70 g
Dimensions [Buckled]: 29.21 x 3.81 x 3.18 cm

Orientation for dimensions: buckled, gathered, and elongated.

i Replacement chin strap sold separately from the Ridgeline T2 Full Brim.

Updated as of 02.26

INSTRUCTIONS

To Remove Chin Strap from Hard Hat

1. Locate the bottom of the tab where the chin strap connects to the hat.
2. Push and hold the bottom of the tab.
3. Pull strap firmly to detach it from the hat.
4. Repeat for the other three points.

To Attach Chin Strap to Hard Hat

1. Firmly press each of the four tabs on the chin strap into their respective slots on the hat.
2. Ensure that each tab firmly locks into place for a secure fit.

i Ridgeline T2 with Mips® system must be worn with chin strap. Chin strap is optional for Ridgeline T2 without the Mips® system.



LEARN MORE
ABOUT THE RIDGELINE T2'S
KEY FEATURES